Section VI Budget – Daedalus Projects, Inc.





First Unitarian Society of Plainfield Preservation Plan Plainfield, NJ

February 24, 2008

Preservation Plan Estimate

Design Architects:

Historic Building Architects, LLC.

Cost Estimator:

Daedalus Projects Incorporated 112 South Street Boston, MA 02111 (617) 451 2717 (617) 451 2679



First Unitarian Society of Plainfield
Preservation Plan
Plainfield, NJ

Introduction

Project Description:

Exterior masonry stabilization and restoration including stone replacements, repairs, re-pointing and cleaning. Stained glass window restoration and repair.

Roofing replacement including gutters and downspouts.

Code compliance upgrades.

Heating system replacement and repairs.

Project Particulars:

Draft Preservation Plan for First Unitarian Society of Plainfield; Sections III - V, and Appendixes D, E & F dated January 11, 2008 prepared by Historic Building Architects, LLC.

Draft Summary of Observations and Recommendations Regarding Structural Conditions of the First Unitarian Society of Plainfield Report dated January 25, 2008 prepared by Robert Silman Associates, PC.

Mechancial and Electrical Report dated February 19, 2008 prepared by Princeton Engineering Group.

Detailed quantity takeoff from these documents where possible.

Daedalus Projects, Inc. experience with similar projects of this nature.

Discussion and review with the Design Team.

Project Assumptions:

Project will be publicly bid.

Our costs assume that there will be competitive bidding in all trades and sub-trades i.e. at least three bids per trade Unit rates are based on current dollars. An escalation allowance to mid-point of construction has been included in the unit rates.

The Total Construction Cost reflects the fair construction value of this project and should not be construed as the prediction of the lowest bid.

Design and Pricing Contingency markup is an allowance for unforeseen design issues, design detail development and specification clarifications.

General Conditions and Requirements value covers temporary staging and access, public safety measures, site supervision personnel, site office overhead, temporary heat and consumable utilities.

Overhead and profit markup is calculated on a percentage basis of direct construction costs. The value covers Contractor's insurances and profit.

Construction will be phased over many years. Escalation has been included at 5% per year. For items that are Immediate, escalation has been included at 5% reflecting 1 - 2 years out (2009). Mid-term items, included at 30% reflects 5 years out (2013). Long-term items, included at 65% reflects 10 years out (2018).



First Unitarian Society of Plainfield Preservation Plan Plainfield, NJ

Introduction

Project Exclusions:

Construction Contingency.

City permitting and requirements.

Design fees and other soft costs.

Interest expense.

Owner's project administration.

Construction of temporary facilities.

Printing and advertising.

Specialties, loose furnishings, fixtures and equipment beyond what is noted.

Site or existing condition surveys and investigations.

Hazardous materials survey, report and removal.

Police details and street/sidewalk permits.

Geotechnical surveys.



 Preservation Main Summary
 \$1,530,951
 \$784,001
 \$1,206,590

 26,135 SF
 26,135 SF
 26,135 SF
 26,135 SF

	26,135 SF	26,135 SF	26,135 SF
ELEMENT		COST	
	Immediate	Mid-term	Long Term
01-GENERAL REQUIREMENTS	\$139,178	\$71,500	\$108,900
	,	. ,	,
Exterior Restoration			
02-SITEWORK	\$126,775	\$3,218	\$47,916
03-CONCRETE	\$42,966	•	
04-MASONRY	\$360,258	•	\$10,890
05-METALS	\$19,404	•	Ψ10,030
06-WOOD - ROUGH & FINISH CARPENTRY		•	¢50 270
	\$95,517	•	*
07-THERMAL & MOISTURE PROTECTION	\$237,897	•	
08-OPENINGS DOORS & WINDOWS	\$276,070	•	
10-MISCELLANEOUS	\$47,263	\$2,574	\$8,712
Exterior Restoration SubTotal (including all markups)	\$1,206,150	\$512,295	\$452,135
MEP Systems			
15-FIRE PROTECTION			\$87,987
15-PLUMBING	\$4,158	\$26,426	\$79,933
15-HVAC	\$23,354	\$39,640	\$352,400
16-ELECTRICAL	\$158,112	\$134,140	\$125,235
MEP Systems SubTotal (including all markups)	\$185,624	\$200,206	\$645,555
Estimate Construction Cost Total	\$1,530,951	\$784,001	\$1,206,590
		·	



 Preservation Main Summary
 \$1,530,951
 \$784,001
 \$1,206,590

 26,135 SF
 26,135 SF
 26,135 SF
 26,135 SF

ELEMENT		COST	20,100 01
	Immediate	Mid-term	Long Term
		2 2 - 2 - 2 - 2	3 : 2:
Alternates (including all markups)			
Install new below grade drains	\$39,986		
Restoration of Church roofs and flashings immediately in lieu of Mid-term	\$225,247		
Replace slate roofing w/new ashpalt shingle in lieu of slate, Parish Hall	(\$86,505)		
Eliminate new lift and install new wood ramp to new door	(\$37,422)		



 Exterior Preservation Details
 Details SubTotal
 \$1,345,327
 \$583,795
 \$561,035

 10,100 SF
 10,100 SF
 10,100 SF
 10,100 SF

					10,100 35	10,100 55	10,100 35
CODE	ELEMENT	QUANTITY	UNIT	UNIT RATE		COST	
					Immediate	Mid-term	Long Term
	01-GENERAL REQUIREMENTS						
	NJHT Project Sign - allowance provided	1	AL	\$500.00	\$500		
	Overheads				\$120,000	\$50,000	\$60,000
	Profit on overheads	10%			\$12,050	\$5,000	\$6,000
	Escalation Allowances for Phasing						
	Immediate	5%			\$6,628		
	Mid-Term	30%				\$16,500	
	Long Term	65%					\$42,900
	01-GENERAL REQUIREMENTS TOTAL				\$139,178	\$71,500	\$108,900
	02-SITEWORK						
SW1	Remove plant growth, cut back trees, remove tree stumps	3	LOC	\$1,000.00	\$3,000		
SW2	Remove plants and shrubs, Church East Elevation	1	LS	\$1,500.00	\$1,500		
SW3	Clean off biological growth; walls, and windows	9,245	SF	\$1.00	\$9,245		
SW3	Clean off biological growth; roof	14,665	SF	\$0.75	\$10,999		
SW4	Regrade to prevent water ponds	6,195	SF	\$5.00	\$30,975		
SW5	Test and repair below grade drains	1	LS	\$10,000.00	\$10,000		
SW6	Repair and make operational below grade perimeter foundation drains	1	AL	\$10,000.00	\$10,000		
	Remove unstable Powell Terrace, masonry planter bed and entrance steps	375	SF	\$10.00	\$3,750		
	Remove deteriorated brick walls and uneven slate, Stevens Wing terrace	375	SF	\$5.00		\$1,875	
	Archaeology observation request by NJHT	1	AL	\$5,000.00	\$5,000		
SW13	Replace contemporary concrete sidewalks w/new slate	1	LS	\$20,000.00			\$20,000
SW14	Remove wooden ramp and concrete foundations, North - Parish Hall	1	LS	\$2,000.00	\$2,000		



					10,100 31	10,100 31	10,100 31
CODE	ELEMENT	QUANTITY	UNIT	UNIT RATE		COST	
					Immediate	Mid-term	Long Term
	Remove wooden stairway and concrete foundations, West - Parish Hall	1	LS	\$2,000.00			\$2,000
	New stampcrete path to lift entrance	20	LF	\$50.00	\$1,000		
	New window well		LOC	\$1,000.00	\$1,000 \$4,000		
			LF	\$1,000.00	·		
	Install new below grade drain				Alternate		
	Connection to City storm drain		LOC	\$2,500.00	Alternate	#4.07 5	#00.000
	Subtotal Subtotal				\$91,469		
	Design and Pricing Contingency	20%			\$18,294		
	Profit	10%			\$10,976	\$225	\$2,640
	Escalation Allowances for Phasing						
	Immediate	5%			\$6,037		
	Mid-Term	30%				\$743	
	Long Term	65%		ļ			\$18,876
	02-SITEWORK TOTAL				\$126,775	\$3,218	\$47,916
	03-CONCRETE						
CO2. MR's	Remove and repair stucco, Parish Hall - quantity provided	300	SF	\$16.50		\$4,950	
	Remove and repair stucco, Stevens Wing	630		\$16.50		, , , , , , ,	\$10,387
CO5	Clean biological growth from terrace paving, Stevens Wing	375		\$2.50	NIC		* 10,001
	New footings for step entrance restoration - SW9 above	50		\$75.00	\$3,750		
	Repair steps and rebuild CMU walls, Basement areaway Stevens Wing		FLT	\$4,000.00	\$4,000		
	The state of the s			¥ 1,000100	¥ 1,000		
	Clean out debris. Replace existing basement rat slab under Church -	1,500	SF	\$7.50	\$11,250		
	excludes existing unexcavated area	,		·	. ,		
	New footing for sidewalls at North & East Porch Entrances	2	LOC	\$2,000.00	\$4,000		
	New footing for lift in Library	1	LS	\$8,000.00	\$8,000		
	Subtotal				\$31,000	\$4,950	\$10,387



					10,100 35	10,100 35	10,100 3F
CODE	ELEMENT	QUANTITY	UNIT	UNIT RATE		COST	
					Immediate	Mid-term	Long Term
	Design and Pricing Contingency	20%			\$6,200	\$990	•
	Profit	10%			\$3,720	\$594	\$1,246
	Escalation Allowances for Phasing						
	Immediate	5%			\$2,046		
	Mid-Term	30%				\$1,960	
	Long Term	65%					\$8,912
	03-CONCRETE TOTAL				\$42,966	\$8,494	\$22,622
	04-MASONRY						
DDO	Class high sign arough from height in gloded in Cas 00						
BR2	Clean biological growth from brick - included in Sec 02	_		#450.00	#450		
BR3	Remove white efflorescence staining - 30" x 12"		LOC	\$150.00	\$150		
BR5	Remove tar from brick chimney, Parish Hall		LOC	\$250.00	\$250	ФО 000	
ST3	Remove tar from stone towers, Church		LOC	\$500.00	Φ0.500	\$2,000	
BR8	Rebuilding and structural stabilization of arch above basement window		LOC	\$2,500.00	\$2,500		
BB0 BB0	Infill window W021		LOC	\$2,000.00	\$2,000		
	Rebuilding and structural stabilization of brick and stone; assumed 5%	90	SF	\$65.00	\$5,845		# = 000
BR8,	Restore brick chimney, East - Stevens Room	1	LS	\$5,000.00	Ф0.000		\$5,000
BR11	New brick terrace walls, Stevens Wing	60	SF	\$60.00	\$3,600	4.0 7.5 0	
	Bluestone terrace paving, Stevens Wing	375	SF	\$50.00	•	\$18,750	
BR11	Clean and rebuild brick piers and foundation wall below Church/Parish Hall in crawl space	45	LF	\$125.00	\$5,625		
MR2	Repoint exterior stone, Church - quantity provided	2,500	SF	\$30.00	\$75,000		
MR3	Repoint interior basement stone, Church - 70% allowance provided	1,260	SF	\$30.00	\$37,791		
ST14	Rebuild interior basement stone, Church - 30% allowance provided	540	SF	\$75.00	\$40,501		
MR6, MR9	Remove cracks and unstable stucco, verify structural stability, apply new stucco	1	LS	\$5,000.00	\$5,000		
ST1	Clean biological growth from stone - 75% allowance provided - included in Sec 02						



 Exterior Preservation Details
 Details SubTotal
 \$1,345,327
 \$583,795
 \$561,035

 10,100 SF
 10,100 SF
 10,100 SF
 10,100 SF
 10,100 SF

CODE	ELEMENT		QUANTITY	UNIT	UNIT RATE	, ,	COST	,
						Immediate	Mid-term	Long Term
ST5	Clean paint drips from stone - 5% allowance provided		125	SF	\$2.50	\$313		
ST6	General cleaning all stone facades		2,500	SF	\$2.00	\$5,000		
ST9	Fill minor cracks w/injection repair grout, East Elevation - 20% allowance provided		275	SF	\$20.00	\$5,493		
ST10	Retool unstable stone, East Elevation - quantity provided		850	SF	\$45.00	\$38,250		
ST12	Reattach loose stone - 5% allowance provided		44	SF	\$60.00	\$2,610		
ST15	Rebuild stone steps, Southeast Entrance - Church		1	LS	\$10,000.00	\$10,000		
ST15	Rebuild stone knee wall, including shoring roof structure, North entrance - Church		1	LS	\$15,000.00	\$15,000		
	New lift masonry walls		1	LS	\$5,000.00	\$5,000		
	Su	ubtotal				\$259,926	\$20,750	\$5,000
	Design and Pricing Contingency		20%			\$51,985	\$4,150	\$1,000
	Profit		10%			\$31,191	\$2,490	\$600
	Escalation Allowances for Phasing							
	Immediate		5%			\$17,155		
	Mid-Term		30%				\$8,217	
	Long Term		65%					\$4,290
	04-MASONRY TOTAL					\$360,258	\$35,607	\$10,890
	05-METALS							
MT2	Replace metal rails, North & East Entrances - Church		20	LF	\$75.00	\$1,500		
MT7	Replace missing finials to match existing		6	EΑ	\$5,000.00		\$30,000	
MT8	New light well protective grilles		250	SF	\$50.00	\$12,500		
	Su	ıbtotal				\$14,000	\$30,000	



					10,100 35	10,100 5F	10,100 35
CODE	ELEMENT	QUANTITY	UNIT	UNIT RATE		COST	
					Immediate	Mid-term	Long Term
	Design and Briging Contingency	20%			¢2 000	¢ e 000	
	Design and Pricing Contingency Profit	10%			\$2,800 \$4,600	\$6,000 \$3,600	
		10%			\$1,680	\$3,600	
	Escalation Allowances for Phasing	E0/			\$004		
	Immediate Mid-Term	5% 30%			\$924	¢44.000	
						\$11,880	
	Long Term 05-METALS TOTAL	65%			£40.404	¢E4_400	
	US-INETALS TOTAL				\$19,404	\$51,480	
	06-WOOD - ROUGH & FINISH CARPENTRY						
WT2	Strip paint, sand and repaint trim - based on wall area	1,015	SF	\$1.25	\$1,268		
WT2	Strip paint, sand and repaint trim	3,120	SF	\$1.25		\$3,900	
WT2	Strip paint, sand and repaint trim	3,120	SF	\$1.25			\$3,900
WT5, WT6	Clean, strip paint, prime and paint all woodwork, Parish Hall	3,120	SF	\$5.00		\$15,600	
WT5, WT6	Clean, strip paint, prime and paint all woodwork, Stevens Wing	2,080	SF	\$5.00			\$10,400
WT11	Exterminate vermin in attic space	4	DAY	\$500.00	\$2,000		
WT11	Repair openings created by vermin in roof eaves and gable ends including repair/replacement of rotten/missing wood	1	LS	\$10,000.00	\$10,000		
WT12	Repair structural framing where it pockets into basement walls	4	LOC	\$1,500.00	\$6,000		
WT12	Replace rotten sill plate at South wall of Parish Hall	60	LF	\$25.00	\$1,500		
WT12	Replace/sister floor joist at South wall of Parish Hall	1,010	SF	\$15.00	\$15,147		
WT12	Replace rotten wood; trim, cornice and fascia to match existing - 30% allowance provided	1	LS	\$10,000.00	\$10,000	\$10,000	\$10,000
WT12	Rebuild wood piers, North entrance - Church	2	EΑ	\$2,500.00	\$5,000		
WT13	Consolidate or replace cracked or split wood shingle	1	LS	\$2,500.00		\$2,500	\$2,500
WT14	Replace missing or detached wood trim; cornice, corner post trim, window trim	1	LS	\$5,000.00	\$5,000		



CODE	ELEMENT	QUANTITY	UNIT	UNIT RATE		COST	
					Immediate	Mid-term	Long Term
	Install new wood handrail and balustrade at Parish Hall Entrance	1	LS	\$5,000.00	\$5,000		
	Custom wood finishing at new lift	1	LS	\$8,000.00	\$8,000		
	Subtotal				\$68,915	\$32,000	\$26,800
	Design and Pricing Contingency	20%			\$13,783	\$6,400	\$5,360
	Profit	10%			\$8,270	\$3,840	\$3,216
	Escalation Allowances for Phasing						
	Immediate	5%			\$4,548		
	Mid-Term	30%				\$12,672	
	Long Term	65%					\$22,994
	06-WOOD - ROUGH & FINISH CARPENTRY TOTAL				\$95,517	\$54,912	\$58,370
	07-THERMAL & MOISTURE PROTECTION						
R2	Remove tar, caulking and flashing. Replace w/new LCC, Church	3,345	SF	\$7.50		\$25,088	
R2	Remove tar, caulking and flashing. Replace w/new LCC, Parish Hall	3,868	SF	\$7.50	\$29,010		
R7, R8	Replace contemporary asphalt shingle roofing w/new slate at Church	2,565	SF	\$46.50		\$119,273	
R4, R9	Remove and replace EPDM roofing, South - Parish Hall	900	SF	\$15.00	\$13,500		
R11, R13	Remove (2) roofing system layers and replace w/new LCC standing	1,303	SF	\$30.00		\$39,083	
	seam metal roofing, Church side aisles only						
R11, R13	Remove and replace LCC flat pan roofing, Parish Hall dormers	75	SF	\$30.00	\$2,250		
R17-20	Remove and replace slate roofing, Parish Hall	2,370	SF	\$47.25	\$111,983		
	Remove and replace slate dormer cheek walls, Church	80	SF	\$52.00		\$4,160	
FL6, FL3,	Remove and replace all gutters and downspouts, connect to new below	670	LF	\$20.00	\$13,400		
FL4	grade storm drain						
FL6	Replace flashings at all roof penetrations, Parish Hall	1	LS	\$1,500.00	\$1,500		
FL7	Remove flashings and replace w/new LCC; window sill, roof/dormer						
	junction, valleys, roof/chimneys - included in R2						



					10,100 35	10,100 3F	10,100 3F
CODE	ELEMENT	QUANTITY	UNIT	UNIT RATE		COST	
					Immediate	Mid-term	Long Term
							4- 0 c :-
	New asphalt roofing, Stevens Wing	5,285	SF	\$10.00	.		\$52,849
	Subtota				\$171,643	\$187,603	\$52,849
	Design and Pricing Contingency	20%			\$34,329	\$37,521	\$10,570
	Profit	10%			\$20,597	\$22,512	\$6,342
	Escalation Allowances for Phasing				.		
	Immediate	5%			\$11,328		
	Mid-Term	30%				\$74,291	
	Long Term	65%					\$45,344
	07-THERMAL & MOISTURE PROTECTION TOTAL				\$237,897	\$321,927	\$115,105
	08-OPENINGS DOORS & WINDOWS						
WD8	Replace rotten basement window - Stevens Room	2	EA	\$1,500.00	\$3,000		
WD8	Replace Church basement window w/new, install new ss screen	5	EΑ	\$1,500.00	\$7,500		
WD7	Restore wood window frame for stained glass window, strip, prime and paint	7	EA	\$1,000.00	\$7,000		
WD7	Double hung and casement window to be restored (W140, W148 and 3 roof dormers), Parish Hall	5	EA	\$1,000.00		\$5,000	
	Convert W114 into lift access door at Parish Hall Library	1	EΑ	\$3,000.00	\$3,000		
WD2	Strip, prime and paint windows with minor repairs, Parish Hall	11	EΑ	\$500.00	·	\$5,500	
WD16	Remove metal grate on window	4	EΑ	\$250.00	\$1,000		
WD18	Remove Plexiglas protective glazing at all windows	14	EA	\$250.00	\$3,500		
WD18	Remove Plexiglas over contemporary window, Stevens Wing	4	EΑ	\$250.00	\$1,000		
	New leaded glass windows to replace W103, W104 & W105	3	EΑ	\$5,000.00			\$15,000
WD2	Minor glass pane repair at basement window, Stevens Wing	6	EΑ	\$200.00			\$1,200
WD2	Restore prime and paint at basement window, Stevens Wing	6	EΑ	\$250.00	\$1,500		
WD5	Replace rotten window sill, Stevens Wing	3	EΑ	\$500.00	\$1,500		



					10,100 SF	10,100 SF	10,100 St
CODE	ELEMENT	QUANTITY	UNIT	UNIT RATE		COST	
					Immediate	Mid-term	Long Term
	Replace door, Parish Hall West Elevation	2	LEAF	\$3,500.00	\$7,000		
	Stained glass and leaded windows - Budgets provided by Femenella & Associates		AL	ψο,σσσ.σσ	\$156,185	\$9,362	\$44,50
	New protective glazing (not recommended by Consultants)	1	AL	\$25,851.00			\$25,85
	Remove and replace flat roof skylight	1	EA	\$3,000.00	\$3,000		
	New door for lift access w/hardware	1	LS	\$4,000.00	\$4,000		
	Subtotal				\$199,185	\$19,862	\$86,55
	Design and Pricing Contingency	20%			\$39,837	\$3,972	\$17,31
	Profit	10%			\$23,902	\$2,383	\$10,38
	Escalation Allowances for Phasing						
	Immediate	5%			\$13,146		
	Mid-Term	30%				\$7,865	
	Long Term	65%					\$74,26
	08-OPENINGS DOORS & WINDOWS TOTAL				\$276,070	\$34,083	\$188,51
	10-MISCELLANEOUS						
MS1	Remove surface mounted conduit and repair wood behind	1	LS	\$1,500.00		\$1,500	\$1,50
MS2	Remove surface mounted contemporary fixture and replace w/historic replica	1	LS	\$2,500.00			\$2,50
MS3	Remove surface mounted attachments and repair wood/stone behind	1	LS	\$2,000.00	\$2,000		
	NJHT Marker - allowance provided	1	AL	\$100.00	\$100		
	Vertical access lift equipment and installation	1	LS	\$32,000.00	\$32,000		
	Subtotal				\$34,100	\$1,500	\$4,00



				10,100 35	10,100 35	10,100 SF
CODE	ELEMENT	QUANTITY UNIT	UNIT RATE		COST	
				Immediate	Mid-term	Long Term
	Design and Pricing Contingency	20%		\$6,820	\$300	\$800
	Profit	10%		\$4,092	\$180	
	Escalation Allowances for Phasing					
	Immediate	5%		\$2,251		
	Mid-Term	30%			\$594	
	Long Term	65%				\$3,432
	10-MISCELLANEOUS TOTAL			\$47,263	\$2,574	
				·	•	,
	Estimate Construction Cost Total			\$1,345,327	\$583,795	\$561,035



					10,100 31	10,100 31	10,100 3
ELEMENT		YTITMAU	UNIT	UNIT RATE		COST	
					Immediate	Mid-term	Long Term
15-FIRE PROTECTION							
New sprinkler system		10,100	GSF	\$4.00			\$40,39
	Subtotal						\$40,39
Design and Pricing Contingency		20%					\$8,0
Profit		10%					\$4,84
Escalation Allowances for Phasing							
Immediate		5%					
Mid-Term		30%					
Long Term		65%					\$34,60
15-FIRE PROTECTION TOTAL							\$87,9
15-PLUMBING							
Replace existing Sump Pump		1	LS	\$1,000.00	\$1,000		
Water Closet; repairs		1	AL	\$2,000.00	\$2,000		
Water Closet (new)		8	EΑ	\$2,000.00			\$16,0
Valves & Specialties		1	LS	\$500.00			\$5
Permits & Fees		1	LS	\$700.00			\$7
Testing & sterilize		1	LS	\$900.00			\$9
Shop Drawings		1	LS	\$1,000.00			\$1,0
Replace Trap		1	LS	\$7,500.00		\$7,500	
Grease Interceptor		1	LS	\$5,000.00		\$5,000	
Valves & Specialties		1	LS	\$500.00		\$500	
Permits & Fees		1	LS	\$700.00		\$700	
Testing & sterilize		1	LS	\$1,200.00		\$1,200	
Shop Drawings		1	LS	\$500.00		\$500	



ELEMENT		QUANTITY	UNIT	UNIT RATE	10,100 01	COST	10,100 01
					Immediate	Mid-term	Long Term
Domestic Cold Water		1	LS	\$5,000.00			\$5,000
2" Water Service w/ meter		1	LS	\$5,000.00			\$5,000
Gas (modifications)		1	LS	\$2,500.00			\$2,500
Demolition		1	LS	\$1,250.00			\$1,250
Valves & Specialties		1	LS	\$500.00			\$500
Permits & Fees		1	LS	\$850.00			\$850
Testing & sterilize		1	LS	\$1,000.00			\$1,000
Shop Drawings		1	LS	\$1,500.00			\$1,500
•	Subtotal				\$3,000	\$15,400	
Design and Pricing Contingency		20%			\$600	\$3,080	
Profit		10%			\$360	\$1,848	\$4,404
Escalation Allowances for Phasing							
Immediate		5%			\$198		
Mid-Term		30%				\$6,098	
Long Term		65%					\$31,489
15-PLUMBING TOTAL					\$4,158	\$26,426	\$79,933



	QUAITII I	UNII	UNIT RATE		COST	
				Immediate	Mid-term	Long Term
15-HVAC						
Combustion Air Supply	1	LS	\$3,000.00	\$3,000		
Forced Air Heater for vestibule	1	LS	\$5,000.00	\$5,000		
Controls for classrooms	1	LS	\$2,600.00	\$2,600		
Rotate registers in Parish Hall	1	LS	\$2,000.00	\$2,000		
Valves & Specialties	1	LS	\$350.00	\$350		
Permits & Fees	1	LS	\$400.00	\$400		
Demolition	1	LS	\$1,500.00	\$1,500		
Testing & Balancing	1	LS	\$500.00	\$500		
Shop Drawings	1	LS	\$1,500.00	\$1,500		
New Split ducted System (Ministers office)	2	EΑ	\$5,000.00		\$10,000	
New cooling unit	2	EΑ	\$5,000.00		\$10,000	
Valves & Specialties	2	LS	\$200.00		\$400	
Permits & Fees	2	LS	\$250.00		\$500	
Demolition	2	LS	\$200.00		\$400	
Testing & Balancing	2	LS	\$400.00		\$800	
Shop Drawings	2	LS	\$500.00		\$1,000	
New Split ducted System (classroom)	5	EΑ	\$12,250.00			\$61,250
Valves & Specialties	1	LS	\$800.00			\$800
Permits & Fees	1	LS	\$500.00			\$500
Demolition	1	LS	\$1,000.00			\$1,000
Control System	1	LS	\$82,500.00			\$82,500
Testing & Balancing	1	LS	\$750.00			\$750
Shop Drawings	1	LS	\$15,000.00			\$15,000
	tal			\$16,850	\$23,100	\$161,80



				10,100 01	10,100 01	<u> </u>
ELEMENT	QUANTITY	UNIT	UNIT RATE		COST	
				Immediate	Mid-term	Long Term
Design and Pricing Contingency	20%			\$3,370	\$4,620	\$32,360
Profit	10%			\$2,022	\$2,772	\$19,416
Escalation Allowances for Phasing						
Immediate	5%			\$1,112		
Mid-Term	30%				\$9,148	
Long Term	65%					\$138,824
15-HVAC TOTAL				\$23,354	\$39,640	\$352,400
16-ELECTRICAL						
Interior Electrical						
Demolition						
Demolition work	1	LS	\$5,000.00	\$5,000		
Lighting & Branch Power						
Replace lighting fixtures						
Basement lighting	2,500	SF	\$2.00	\$5,000		
1st floor lighting	5,025	SF	\$4.00	\$20,100		
Parish Hall lighting	5,630	SF	\$4.00	\$22,520		
Replace emergency lighting	13,155	SF	\$0.40	\$5,262		
Replace stage lighting in community room	1	LS	\$7,500.00	\$7,500		
Replace all duplex receptacles	13,155	SF	\$0.30	\$3,947		
LV wiring to be concealed in surface raceway or conduits	1	LS	\$15,000.00	\$15,000		
New lift service	1	LS	\$5,000.00	\$5,000		
Fire alarm						
New fire alarm system and wiring	10,100	SF	\$1.50	\$15,149		



ELEMENT	QUANTITY	UNIT	UNIT RATE		COST	
				Immediate	Mid-term	Long Term
Telecommunication						
Rough-in				NIC		
Devices and cabling				NIC		
Sound System						
Sound System				NIC		
Security System						
Security system (Rough-in only)				NIC		
Reimbursable						
Temp power & lights	1	LS	\$8,000.00	\$8,000		
Fees & Permits	1	LS	\$1,600.00	\$1,600		
Mid-Term Phase						
Demolition						
Demolition work	1	LS	\$3,500.00		\$3,500	
Lighting & Branch Power						
Replace Stevens wing lighting fixtures	5,630	SF	\$4.00		\$22,520	
Replace emergency lighting	5,630	SF	\$0.40		\$2,252	
Replace all wiring in the building	10,100	SF	\$4.00		\$40,398	
Reimbursable						
Temp power & lights	1	LS	\$8,000.00		\$8,000	
Fees & Permits	1	LS	\$1,500.00		\$1,500	
Long Term Phase						
Demolition						
Demolition work	1	LS	\$3,500.00			\$3,500
Gear & Distribution						
Replace main electrical service, feeders and panelboards required for proposed A/C	1	LS	\$45,000.00			\$45,000



ELEMENT	QUANTITY	UNIT	UNIT RATE	10,100 01	COST	10,100 01
				Immediate	Mid-term	Long Term
Reimbursable						
Fees & Permits		1.0	¢4 000 00			#4.000
Temp power & lights		LS LS	\$1,000.00 \$8,000.00			\$1,000 \$8,000
Subtotal		LS	φο,υυυ.υυ	\$114,078	\$78,170	
Design and Pricing Contingency	20%			\$114,076		
Profit	10%			\$22,616 \$13,689		
Escalation Allowances for Phasing	10 /6			φ13,069	φ9,360	\$0,900
Immediate	5%			\$7,529		
Mid-Term	30%			ψ <i>1</i> ,529	\$30,955	
Long Term	65%				φ30,933	\$49,335
16-ELECTRICAL TOTAL	0376		ŀ	\$158,112	\$134,140	
Estimate Construction Cost Total				\$185,624	\$200,206	\$645,555